


Mounting Instruction



Main parts needed to mount the extrusion



Aluminum profile (A)



End cap (B)




End cap with hole (C)



LED strip (D)



Cover (E)



Metal clip (F)


Tools needed for mounting:

screwdriver


IMPORTANT: The manual presents the simplest mounting procedure.

Mounting Instruction


The first option: 1. Mount the LED strip(D), insert the cover(E), insert the end cap (B) and (C).




2. Mount the metal clip(F) on the wall.




3. Mount the profile on the clip, lead out the power cable.




4. Run the cable to the power source, connect power.




The second option: 1. Mount the LED strip(D), insert the cover(E), insert the end



2. Mount the metal clip(F) on the corner.



3. Mount the profile on the clip, lead out the power cable.



4. Run the cable to the power source, connect power.

